



xShaping


Simplify the shaping of individual parts, including toe notches, cut out around columns, clip and radius corners



Not all jobs involve right angles. Wall angles, floor levels and customer preferences can pose irregular shaping challenges. xShaping provides the capability to parametrically shape assemblies, parts, and routes utilising both simple and advanced constraints. xShaping also gives access to the CAM Editor for easily adding operations to parts for machining, such as grommet holes, electrical chases and plumbing cutouts.

Key Features

- Parametric assembly shaping (advanced constraints)
- Parametric part shaping (advanced constraints)
- Parametric route shaping (advanced constraints)
- Part level CAM editor and reports views
- Split parts
- Add & modify operations on parts
- Library parts
- Replace part w/library parts or DXFs
- Exploded assembly view
- Edit part shape from room level
- Combine multiple assemblies/toes in elevation view



We are here for you!

Our customer service representatives and support technicians are on hand to help you become more successful. If you have any questions or requests, please contact us.

Telephone: +64 (7) 392 1001

Email: info@joineryit.co.nz

eSupport: esupport.ps.hexagonmi.com

Customer Portal: www.customers.ps.hexagonmi.com

| Visit jit2022.nz